



Portata Max
Charge Max
Max Capacity
280kg
3 OPERATEURS

Portata Max
Charge Max
Max Capacity
280kg
3 OPERATEURS

Portata Max
Charge Max
Max Capacity
400kg
3 OPERATEURS

Portata Max
Charge Max
Max Capacity
400kg
3 OPERATEURS

(Jib rientrato)
(Jib rentre')
(Jib inside)

Rotazione 360°
Rotation 360°
360° Continuous

Continui
Continus
Rotation

- *- Area di lavoro con bracci stab. totalmente estesi
- ** - Area di lavoro con bracci stab. parzialmente estesi
- *- Courbe de travail avec bras stabilisateurs toutes ouvertes
- ** - Courbe de travail avec bras stabilisateurs partiellement ouvertes
- *- Working area with stabilisers booms completely extended
- ** - Working area with stabilisers booms partially extended



INSEGNARE PER LAVORARE - INSEGNARE - STEEL